



LEROY SURVEYORS & ENGINEERS, INC.

Surveying • Engineering • Geology • Septic Design • GPS • GIS Mapping

Exhibit 3.b

Arborist Report

David Rich, Mustard Seed Legacy Development, LLC

RE: Champions Centre Arborist Report, DuPont WA

September 6, 2023

Page 2 of 27

THE PROPOSED DEVELOPMENT AND SITE IMPROVEMENTS

The overall site currently includes 4 parcels comprising just over 21 acres. A proposed boundary line adjustment will reduce the parcels 4 into 3: parcels A, B & C.

Parcel A (3.20 acre) will be a commercial lot to include the construction of approximately 26,000 square foot religious assembly that will have a maximum congregation capacity of 350 people. The architectural footprint for this Religious Assembly is very unique to allow for the existing grove of Landmark Oregon white oak trees that sit on an existing knoll to be protected and remain on-site. This parcel will include a total of 135 parking stalls.

Parcel B (0.92 acres) is also a commercial lot to include the construction of approximately 3,000 square foot eating and drinking establishment. The maximum capacity is unknown at this time, but will include a 38 parking stalls.

Parcel C (17.17 acres) is an existing wetland, wetland buffer, stream, stream buffer and Fema Flood Zone A. This parcel will be deeded to the City of DuPont upon the recording of the boundary line adjustment.

TREE NUMBERING SYSTEM

Each tree onsite is marked with a 1" x 3.5" aluminum tag indicating tree number. Offsite trees are not tagged. The numbering systems in this report, and on associated project drawings are, generally: onsite trees 1-77; wetland buffer and offsite trees 101-138; street trees 8000 – 8014. (Trees 119 and 120 were initially inventoried with onsite trees, but are within the street right-of-way and are street trees.)

TREES OF NON-SIGNIFICANCE

Trees not shown on the sheets (and/or appear to be out of sequence) are either too small or are a non-regulated species. They are removed from the sheets and the attached inventory to reduce clutter, and they include the following tree numbers:

Trees of Non-Significance				
26	44	72	112	133
28	48	74	113	
29	55	101	114	
32	56	107	115	
43	57	110	116	

TREE INSPECTION

I visually inspected each tree from the ground. I performed a Level 1 risk assessment.¹ This is the standard assessment for populations of trees near specified targets, conducted in order to identify obvious defects or specified conditions such as a pre-development inventory. This is a limited visual assessment focuses on identifying trees with imminent and/or probable likelihood of failure, and/or other visible conditions that will affect tree retention.

I recorded tree species and size (DBH). I estimated the average dripline of each tree. I rated the condition of each tree, both health and structure. A tree's structure is distinct from its health. This inspection identifies what is visible with both.

High-risk trees can appear healthy in that they can have a dense, green canopy. This may occur when there is sufficient sapwood or adventitious roots present to maintain tree health, but inadequate strength for structural support.

Conversely, trees in poor health may or may not be structurally stable. For example, tree decline due to root disease is likely to cause the tree to be structurally unstable, while decline due to drought or insect attack may not.

One way that tree health and structure are linked is that healthy trees are more capable of compensating for structural defects. A healthy tree can develop adaptive growth that adds strength to parts weakened by decay, cracks, and wounds.

This report identifies unhealthy trees based on existing health conditions and tree structure, and specifies which trees are most suitable for preservation.²

No invasive procedures were performed on any trees. The results of this inspection are based on what was visible at the time of the inspection.

¹ Companion publication to the ANSI A300 Part 9: Tree Shrub and Other woody Plant Management – Standard Practices, Tree Risk Assessment. 2011. ISA.

² Companion publication to the ANSI A300 Part 5: Tree Shrub and Other woody Plant Maintenance – Standard Practices, Managing Trees During Construction. 2008. ISA.

The attached inventory summarizes my inspection results and provides the following information for each tree:

Retain Tree? indicates if tree is proposed for retention.

Tree Category: Landmark, Specimen, Street or Hazard, as defined by municipal code.

Tree number as shown on tag in the field (for onsite trees), and on attached exhibit.

DBH stem diameter in inches measured 4.5 feet from the ground.

Tree Species common name.

Dripline measured branch extension into the subject parcel as measured from an existing fence for offsite trees.

Healthy? Well formed? Safe? in addition to species and DBH, these criteria define a landmark tree (or conversely, define a hazard tree). Trees in poor health are identified under the 'Health' column. Many of the oak trees that are stressed, or exhibiting only *fair* health, appear healthy enough to retain, but the lack of a non-healthy indication does not imply a tree in good to excellent condition.

Comments on Condition visible at time of inspection, which includes:

Asymmetric canopy - the tree has an asymmetric canopy from space and light competition from adjacent trees.

Branch dieback - mature branches in canopy are dying/dead.

Bow in trunk - a trunk lean characterized by the top of the tree leaning over (common with edge trees).

Canker - disease cankers are established on trunk/branches.

Crack - separation of wood fibers and predisposed to failure.

Dead - tree is dead.

Deadwood - large and/or multiple dead branches throughout canopy.

Decay - process of wood degradation by microorganisms resulting in weak and defective structure.

Diseased - foliage and trunk/stems are diseased.

Dogleg in trunk - trunk with a bow or defective bend (90°) in trunk often half way of further up the trunk.

Double leader - the tree has multiple stem attachments, which may require maintenance or monitoring over time.

Foliar disease - foliage is diseased with manageable fungus.

Grove trees - tree should be retained only as a grove tree, not stand-alone.

Gummosis - oozing resin, indicating stress/decline.

Heart rot - fungal infection with interior of tree decayed.

Included bark - an inclusion of bark at the attachment of multiple leaders that prevents a wood-to-wood attachment.

Insect Injury - active insect injury affecting tree health.

Ivy - dense ivy prevents a thorough inspection, and other defects may be present.

Ganoderma —a wood-decaying fungi inside the tree eating the wood.

LCR - live crown ratio: the ratio of crown length to total tree height. Stand-alone trees with a LCR of 30 and lower are at increased risk of failure.

Lean - angle of the trunk from vertical.

Multiple leaders - the tree has multiple stem attachments, which may lead to tree failure and require maintenance or monitoring over time.

Poor structure - tree's structure is deformed and defective/unsightly.

Previous failure - tree trunk previously broken and defective.

Response wood - new wood produced in response to loads that indicate uneven loading from wind or end-weight.

Slender - tree lacks adequate trunk taper to stand lone (poor height/trunk diameter ratio).

Stem Canker - disease canker on trunk/branches.

Sweep in trunk - characterized by a leaning lower trunk and a more upright top.

Thinning foliage - low foliage density may indicate stress, or early infection/declining health.

Self-corrected lean - self-corrected leans and sweeps are characterized by a leaning lower trunk and a top that is more upright.

Stumpsprout- tree previously cut at grade with multiple stems and potentially weak attachments.

Suppressed - tree crowded by larger adjacent trees, with defective structure and/or low vigor. Retain tree only as a grove tree, not stand-alone.

Sweep - tree leans away from adjacent trees. Characterized by a leaning lower trunk and a top that is more upright.

Taper - change in diameter over the length of trunks, branches and roots.

Topped – the tree is previously topped and has poor structure and/or stem decay.

Tree leans - trunk has significant lean from vertical.

Trunk decay - wood decay is visible in the trunk.

Wound/decay base of trunk - open wound with visible decay in trunk.

DEFINITIONS

DMC 25.10.190.115 S definitions.

“Specimen tree” means an existing *healthy tree which poses no safety hazard* due to potential collapse and is of the following species and minimum diameter measured at breast height; provided, that the measure of multi-trunk trees shall be the sum of the diameters:

- Douglas fir, western red cedar, western hemlock, or big leaf maple: 15 inches;
- Oregon white oak, Pacific yew, or madrone: 12 inches;
- Historic fruit trees: no size limit.

DMC 25.10.040.070 D definitions.

“Drip line” means the imaginary line around a tree aligning with the outer edge of the tree’s canopy.

DMC 25.10.120.005 L definitions.

“Landmark tree” means an existing *healthy, well-formed tree which poses no safety hazard due to potential collapse* and that is of the following species, trunk type, and minimum diameter measured at breast height:

Species		
Trunk-type	Oregon white oak, Pacific yew, or Pacific madrone	Douglas-fir, Western red-cedar, Western hemlock, or Bigleaf maple
Single-trunk	24 inches	30 inches
Multi-trunk (sum of diameters)	30 inches	45 inches

[Above *italics are mine.*]

DMC 25.10.190.160 S definitions.

“Street tree” means a tree planted or retained in a public right-of-way or parking strip.

LANDMARK TREES

Twenty-two (22) trees meet the definition of landmark tree. The following two tables separate them by oaks (top table) and non-oak species (lower table). (Tree 119 is a landmark-size oak and stands in the street right-of-way. This tree will be retained, and is not included in the retention calculation because of its designation as a *street tree*.)

LANDMARK OAK TREES				
Location	Tree No.	DBH	Species	Proposed Action
	3	30"	Oregon oak	Retain
	6	25"	Oregon oak	Retain
	9	28"	Oregon oak	Retain
	16	25"	Oregon oak	Remove
	20	24"	Oregon oak	Remove
	21	30"	Oregon oak	Remove
	127	14,16,18"	Oregon oak	Retain
Total Oaks = 7		Retained Oaks = 4		Percent Retained = 57%

LANDMARK NON- OAK TREES				
Location	Tree No.	DBH	Species	Proposed Action
	24	54"	Douglas-fir	Remove
	27	54"	Douglas-fir	Remove
100' WB	30	34"	Douglas-fir	Remove
	31	31"	Douglas-fir	Remove
	60	32"	Douglas-fir	Remove
	62	35"	Douglas-fir	Remove
	69	34"	Douglas-fir	Retain
	70	35"	Douglas-fir	Retain
75' WB	103	31"	Douglas-fir	Retain
75' WB	105	38"	Douglas-fir	Retain
75' WB	106	43"	Douglas-fir	Retain
75' WB	108	38"	Douglas-fir	Retain
75' WB	109	36"	Douglas-fir	Retain
75' WB	117	32"	Bigleaf maple	Retain
75' WB	118	30"	Bigleaf maple	Retain
Total Non-Oaks = 15		Retained Non-Oaks = 9		Percent Retained = 60%

HAZARD TREES OF LANDMARK SIZE

Based on the above definitions, vis-à-vis healthy, well-formed and safe trees, the following table identifies six (6) landmark-size trees that do not exhibit these attributes, and are established here as *hazard trees*.

These trees are excluded from retention calculations. All are proposed for removal. See attachment 4 for photo illustrations of existing conditions.

Table of Six (6) Hazard Landmark-Size Trees

Tree No.	DBH	Species	Comments on Condition
2	13,20,24"	Bigleaf maple	Multiple leaders along trunk axis, previous leader failure and open wound with decay, included bark with response wood present
22	56"	Douglas-fir	Recent failure of the top of the tree, trunk decay visit at failure, 7.5" sound wood at base observed after extracting a wood core, scaffold branch failure in upper canopy at previous topping wound, dead hanging branch in upper canopy
63	32"	Douglas-fir	Resin oozing on lower portion of trunk, 6" sound wood from removed core, then discolored wood further in trunk, very thin foliage, some branch dieback, and suspect root rot infection.
66	33"	Douglas-fir	Previous rootplate failure and with an obvious sweep in the trunk, low LCR, thin branches throughout canopy
67	(11) 9-26"	Bigleaf maple	Multiple leaders at single attachment near grade (tree was likely cut to grade decades ago), bark inclusions present at most attachments, previous failure of structural branches, <i>Ganoderma</i> fungus fruiting bodies on lower trunk.
77	24"	Oregon oak	Dense ivy covering trunk, trunk leans, asymmetric structure, deadwood throughout canopy, thin branches, low LCR.

An additional eight (8) hazard trees of specimen size are indicated separately in the inventory table of attachment 5. (No photographs are provided for these trees.)

TREE RETENTION

Tree retention shall constitute an integral design goal in all public and private site design processes. Retention is particularly desired for trees that are especially large, well-formed, historic, grouped, close to a sensitive area, visually prominent, part of a recognizable landmark, or valuable as wildlife habitat. (DMC25.120.030 Tree retention)

Very few of the existing trees stand alone, and most in close proximity with other trees of similar species and/or age. This is particularly evident with the largest stand of native oak trees just north of Dupont-Steilacoom Road. This group includes 21 trees, and all save two (2) are oak.

Overall, these oaks are in fair to poor condition, and for two (2) primary reasons: neglect (resulting in competition from invasive bramble and vines), and poor structure (from close proximity to each other resulting in competition for light and space).


The image right, and also on the following page, show the disarray of this grove of oak trees. Invasive bramble and vine has dominated both the understory of the forest floor, and also the upper canopy of several trees.

The invasive bramble has out competed native understory shrubs within the stand, and also competes with the oaks for available rainwater.



Several tree trunks are covered in dense ivy, some recently cut and killed, and some still living. The dense ivy competes for light and space, resulting in skinny trees (a high height/diameter ratio, or H/D) and tall trees with few or no low branches (low live crown ratio (LCR)). The result is stressed and poorly formed trees. These conditions of slenderness and low LCR affect tree health and stability as evidenced by an oak recently pulled to the ground by the dense ivy.

Removal of the ivy is insufficient to cause the trees to grow new low branches on their trunks, reversing the H/D and LCR conditions, partly because of species characteristics, and particularly because of their existing close proximity to each other.



The native Oregon oak typically thrives in a 'hands-off' environment, and rarely requires intervention by people for optimal growth (and in many cases, neglecting them, or the lack of 'over care' is the best option). In this case, neglect over the decades has resulted in the establishment of the invasive vegetation that has negatively impacted both the health and structure of these trees.

This neglect has impacted the trees' ability to meet criteria that define a landmark tree: *healthy, well-formed tree which poses no safety hazard due to potential collapse.*

REQUIRED TREE RETENTION

The purpose of City's tree retention code is as follows (DMC 25.120.010 Purpose):

(1) The purpose of this chapter is to:

- (a) Protect natural habitats, air quality, and ground water recharge,*
- (b) Improve the appearance of the community,*
- (c) Provide shade and wind protection,*
- (d) Reduce stormwater discharge, and*
- (e) Conserve water supplies.*

(2) This chapter is intended to help achieve these purposes by:

- (a) Retaining trees, without reducing developmental densities from those indicated in the comprehensive plan.*

This project is fortunate to contain the stand of mature native Oregon oaks in full view from both arterial streets that abut the site. This project is aligned with the purpose of the code, and is committed to preserving to the extent possible this existing stand of oaks, and to assure their continued legacy as an asset of the community and the proposed development.

The stated purpose of the retention code is for protection and preservation of environmental benefits and amenities. They are listed below (from the above code) as are the ways in which this project achieves/preserves them.

(a) Protect natural habitats Foremost is the protection of the existing stand of native Oregon oak trees. Although currently there is minimal native understory around these trees, this will be augmented during landscaping with native vegetation that supports native oak groves, as well as the planting of additional oak saplings.

Revised parcel C is 17.17 acres of critical area and associated buffer, all of which will be protected as natural habitat.

(b) Improve the appearance of the community. The site is currently vacant and neglected for years. Invasive ivy and blackberry infest the area of the primary oak grove. Landscaping will remove the invasive plants, and the construction of the proposed improvements and landscaping will be a vast enhancement in the area's appearance, and a contribution to the vitality of the commercial district.

In anticipation of maintaining and preserving the landmark oak grove as a legacy on this site, the project's owner has already 96

white oak trees growing in a private nursery, all to be planted throughout this site.

These oak trees will augment the exiting grove of mature oak trees, assuring continued canopy for decades. Others will be planted throughout the project where soil and site conditions favor the growth of this species.

(c) Provide shade and wind protection.	In addition to the legacy oak grove, several large and mature trees within the wetland buffer are retained, and will maintain existing shade and wind protection.
---	---

Items (d) and (e), reduction of stormwater discharge and conservation of water supplies, along with the stated intent of the code (2) (tree retention and developmental density) will be addressed by others in a separately submitted tree retention modification request.

TREE RETENTION MODIFICATION

DMC allows for a modification of the City's tree retention regulations as follows:

Anyone with an ownership interest in land may request a modification from the provisions of this chapter based on special circumstances pertaining to that land or the trees on it. (25.120.050 Modifications)

A formal request for tree retention modification will be submitted by others for this project.

ATTACHMENTS:

1. Assumptions and Limiting Conditions
2. Certification of Performance
3. Significant Tree Inventory
4. Photographs of Hazard Landmark-Size Trees
5. Tree Retention Plan

ATTACHMENT NO. 1 - Assumptions & Limiting Conditions

- 1) A field examination of the site was made 8/15/2022 and 6/22/2023. My observations and conclusions are as of that date.
- 2) Care has been taken to obtain all information from reliable sources. All data has been verified insofar as possible; however, the consultant/arborist can neither guarantee nor be responsible for the accuracy of information provided by others.
- 3) Unless stated other wise: 1) information contained in this report covers only those trees that were examined and reflects the condition of those trees at the time of inspection; and 2) the inspection is limited to visual examination of the subject trees without dissection, excavation, probing, or coring. There is no warranty or guarantee, expressed or implied that problems or deficiencies of the subject tree may not arise in the future.
- 4) All trees possess the risk of failure. Trees can fail at any time, with or without obvious defects, and with or without applied stress. A complete evaluation of the potential for this (a) tree to fail requires excavation and examination of the base of the subject tree. Permission of the current property owner must be obtained before this work can be undertaken and the hazard evaluation completed.
- 5) Loss or alteration of any part of this report invalidates the entire report.
- 6) Unless required by law otherwise, neither all nor any part of this report, nor copy thereof, shall be conveyed by anyone, including the client, to the public through advertising, public relations, news, sales, or other media without the prior expressed written or verbal consent of the consultant/appraiser, particularly as to value, conclusions, identity of the consultant/appraiser, or any reference to any professional society or institute or to any initialed designation conferred upon the consultant/appraiser as stated in his qualifications.
- 7) The consultant does not assume any liability for the subject tree and does not represent the transfer of such for any risks associated with the tree from the landowner to the consultant. **Risk management is solely the responsibility of the landowner.**

David Rich, Mustard Seed Legacy Development, LLC
RE: Champions Centre Arborist Report, DuPont WA
September 6, 2023
Page 14 of 27


ATTACHMENT NO. 2 - CERTIFICATION OF PERFORMANCE

I, Favero Greenforest, certify that:

- I have personally inspected the trees and the property referred to in this report and have stated my findings accurately.
- I have no current or prospective interest in the vegetation or the property that is the subject of this report and have no personal interest or bias with respect to the parties involved.
- The analysis, opinion, and conclusions stated herein are my own and are based on current scientific procedures and facts.
- My analysis, opinion, and conclusions were developed and this report has been prepared according to commonly accepted arboricultural practices.
- No one provided significant professional assistance to me, except as indicated within the report.
- My compensation is not contingent upon the reporting of a predetermined conclusion that favors the cause of the client of any other party nor upon the results of the assessment, the attainment of stipulated results, or the occurrence of any subsequent events.

I further certify that I am a member in good standing of International Society of Arboriculture (ISA), and the ISA PNW Chapter, I am an ISA Certified Arborist (#PN-0143A) and am Tree Risk Assessment Qualified, and am a Registered Consulting Arborist[®] (#379) with American Society of Consulting Arborists. I have worked as an independent consulting arborist since 1989.


Signed:


GREENFOREST, Inc.


By Favero Greenforest, M. S.

Favero

Greenforest
Date: September 6, 2023



Digitally signed by Favero Greenforest
DN: cn=Favero Greenforest, o, ou,
email=greenforestinc@mindspring.com,
c=US
Date: 2023.09.07 10:12:30 -07'00'



David Rich, Mustard Seed Legacy Development, LLC

RE: Champions Centre Arborist Report, DuPont WA

September 6, 2023

Page 15 of 27

ATTACHMENT NO. 3 – Significant Tree Inventory Table

Retain Tree?	Location	Category	Tree No.	DBH	Species	Dripline (R')	Well formed?	Safe?	Comments on Condition	
N	Onsite	Specimen	1	18"	Douglas-fir	17'		N	Only in grove	Thin canopy, sweep in trunk
N	Onsite	Hazard	2	13,20,24"	Bigleaf maple	32'		N		Multiple leaders attached to trunk, previous leader failure, included bark with response wood, trunk decay
Y	Onsite	Landmark	3	30"	Oregon oak	25'				
Y	Onsite	Specimen	4	18"	Oregon oak	28'		N	Only in grove	Asymmetric canopy, tree leans S
Y	Onsite	Specimen	5	23"	Oregon oak	30'		N	Only in grove	Slight asymmetry
Y	Onsite	Landmark	6	25"	Oregon oak	35'		N	Only in grove	Slight asymmetry
Y	Onsite	Specimen	7	14"	Oregon oak	20'		N	Only in grove	Bend in trunk, tree leans
Y	Onsite	Specimen	8	12"	Oregon oak	16'		N	Only in grove	Leaning trunk
Y	Onsite	Landmark	9	28"	Oregon oak	23'				Dead ivy covers trunk
Y	Onsite	Specimen	10	14"	Oregon oak	18'				
N	Onsite	Hazard	11	13"	Oregon oak	25'	N	N		Dense ivy covers trunk/canopy, 90 degree lean, slender trunk, LCR, thin foliage
Y	Onsite	Specimen	12	13"	Oregon oak	18'		N	Only in grove	Ivy
Y	Onsite	Specimen	13	18"	Oregon oak	20'		N	Only in grove	Ivy
Y	Onsite	Specimen	14	16"	Oregon oak	25'		N	Only in grove	Ivy
Y	Onsite	Specimen	15	20"	Oregon oak	23'				
N	Onsite	Landmark	16	25"	Oregon oak	25'				
Y	Onsite	Specimen	17	12"	Oregon oak	16'		N	Only in grove	
Y	Onsite	Specimen	18	20"	Oregon oak	22'		N	Only in grove	Slight asymmetry



David Rich, Mustard Seed Legacy Development, LLC

RE: Champions Centre Arborist Report, DuPont WA

September 6, 2023

Page 16 of 27

Retain Tree?	Location	Category	Tree No.	DBH	Species	Dripine (R')	Healthy?	Well formed?	Safe?	Comments on Condition
Y	Onsite	Specimen	19	17"	Oregon oak	25'		N	Only in grove	Slight asymmetry
N	Onsite	Landmark	20	24"	Oregon oak	25'				
N	Onsite	Landmark	21	30"	Oregon oak	25'				Dense ivy covering trunk
N	Onsite	Hazard	22	56"	Douglas-fir	35'	N	N	N	Recent top failure, trunk decay, 7.5" sound wood at base, scaffold branch failure, dead hanging branch in upper canopy
N	Onsite	Specimen	23	17"	Bigleaf maple	25'		N		Double leader, trunk sweeps toward street
N	Onsite	Landmark	24	54"	Douglas-fir	32'				Sweep, deadwood
N	Onsite	Hazard	25	26,26"	Oregon ash	16'	N	N	N	Double leader, trunk decay, lean
N	Onsite	Landmark	27	54"	Douglas-fir	35'				Deadwood, hanger
N	100' WB	Landmark	30	34"	Douglas-fir	35'				
N	Onsite	Landmark	31	31"	Douglas-fir	30'				
N	Onsite	Hazard	33	17"	Douglas-fir	25'	N	N	N	Sweep/dogleg in trunks, previous rootplate failure, LCR, thin foliage
N	Onsite	Hazard	34	17"	Douglas-fir	25'	N	N	N	
N	Onsite	Hazard	35	17"	Douglas-fir	25'	N	N	N	
N	Onsite	Specimen	36	25"	Douglas-fir	20'		N	Only in grove	Deadwood, bow in trunk, asymmetric
N	Onsite	Specimen	37	19"	Douglas-fir	18'		N	Only in grove	Asymmetric
N	Onsite	Specimen	38	21"	Douglas-fir	18'		N	Only in grove	Asymmetric
N	Onsite	Specimen	39	18"	Douglas-fir	16'		N		Asymmetric
N	Onsite	Hazard	40	12"	Douglas-fir	12'	N	N	N	Suppressed canopy, thin foliage, asymmetric, slender
N	Onsite	Hazard	41	13"	Douglas-fir	14'	N	N	N	Suppressed canopy, thin foliage, asymmetric, slender

David Rich, Mustard Seed Legacy Development, LLC

RE: Champions Centre Arborist Report, DuPont WA

September 6, 2023

Page 17 of 27

Retain Tree?	Location	Category	Tree No.	DBH	Species	Dripeline (R')	Well formed?	Healthy?	Safe?	Comments on Condition
N	Onsite	Specimen	42	23"	Douglas-fir	30'				Deadwood
N	Onsite	Specimen	45	14,14"	Bigleaf maple	25'				Double leader
N	Onsite	Specimen	46	22"	Bigleaf maple	35'		N		Sweep, asymmetric canopy
N	Onsite	Specimen	47	20"	Douglas-fir	25'				
N	Onsite	Specimen	49	22"	Douglas-fir	20'				Dense ivy on trunk
N	Onsite	Specimen	50	19"	Douglas-fir	20'				Dense ivy on trunk
N	Onsite	Specimen	51	24"	Douglas-fir	20'				Dense ivy on trunk
N	Onsite	Specimen	52	27"	Douglas-fir	20'				Dense ivy on trunk
N	Onsite	Specimen	53	17"	Douglas-fir	20'		N		Asymmetric, thin branches
N	Onsite	Specimen	54	26"	Douglas-fir	25'				Ivy, thin branches
N	Onsite	Specimen	58	18"	Douglas-fir	18'				
N	Onsite	Specimen	59	26"	Douglas-fir	25'				
N	Onsite	Landmark	60	32"	Douglas-fir	30'		N	Only in grove	Asymmetric
N	Onsite	Specimen	61	29"	Douglas-fir	30'		N	Only in grove	Asymmetric
N	Onsite	Landmark	62	32"	Douglas-fir	30'				
N	Onsite	Hazard	63	35"	Douglas-fir	30'	N	N	N	Resin oozing on trunk, 6" sound wood, then discolored wood, thin foliage, some branch dieback, suspect root rot infection.
N	Onsite	Specimen	64	27"	Douglas-fir	25'				
N	Onsite	Specimen	65	25"	Douglas-fir	25'				
N	Onsite	Hazard	66	33"	Douglas-fir	35'	N	N	N	Previous rootplate failure, sweep, LCR, thin branches
N	Onsite	Hazard	67	(11) 9-26"	Bigleaf maple	45'	N	N	N	Multiple leaders, bark inclusions,

David Rich, Mustard Seed Legacy Development, LLC

RE: Champions Centre Arborist Report, DuPont WA

September 6, 2023

Page 18 of 27

Retain Tree?	Location	Category	Tree No.	DBH	Species	Dripeline (R')	Healthy?	Well formed?	Safe?	Comments on Condition
										previous failure, Ganoderma fruiting bodies
Y	Onsite	Specimen	68	29"	Douglas-fir	20'		N		Asymmetric
Y	Onsite	Landmark	69	34"	Douglas-fir	25'		N		Asymmetric
Y	Onsite	Landmark	70	35"	Douglas-fir	30'				
Y	75' WB	Specimen	71	22"	Douglas-fir	20'				
N	Onsite	Specimen	73	22"	Douglas-fir	18'				
Y	Offsite	Street Tree	75	13"	Douglas-fir	16'				
Y	Offsite	Street Tree	76	17"	Douglas-fir	18'				
N	Onsite	Hazard	77	24"	Oregon oak	45'	N	N	N	Dense ivy, lean, asymmetric, deadwood, thin branches, low LCR
Y	100' WB	Specimen	102	28"	Douglas-fir	25'		N		Asymmetric
Y	75' WB	Landmark	103	31"	Douglas-fir	25'				
Y	75' WB	Specimen	104	28"	Douglas-fir	25'		N		Asymmetric
Y	75' WB	Landmark	105	38"	Douglas-fir	40'				
Y	75' WB	Landmark	106	43"	Douglas-fir	35'		N		Dogleg in trunk
Y	75' WB	Landmark	108	38"	Douglas-fir	30'		N		Dogleg
Y	75' WB	Landmark	109	36"	Douglas-fir	35'		N		Dogleg, multiple leaders
Y	75' WB	Specimen	111	26"	Douglas-fir	20'		N		Asymmetric
Y	75' WB	Landmark	117	32"	Bigleaf maple	45'		N		Asymmetric
Y	75' WB	Landmark	118	30"	Bigleaf maple	35'		N		Asymmetric
Y	Offsite	Street Tree	119	32"	Oregon oak	22'				Sidewalk obstruction for rootcrown
Y	Offsite	Street Tree	120	23"	Oregon oak	11'				Sidewalk obstruction for rootcrown
N	Onsite	Specimen	121	28"	Douglas-fir	22'				

Greenforest



Registered Consulting Arborist

David Rich, Mustard Seed Legacy Development, LLC

RE: Champions Centre Arborist Report, DuPont WA

September 6, 2023

Page 19 of 27

Retain Tree?	Location	Category	Tree No.	DBH	Species	Dripine (R')	Healthy?	Well formed?	Safe?	Comments on Condition
N	Onsite	Specimen	122	15"	Douglas-fir	15'				Trunk wound
N	Onsite	Specimen	123	20"	Douglas-fir	16'		N		Asymmetric
N	Onsite	Specimen	124	16"	Douglas-fir	20'		N		Asymmetric
N	Onsite	Specimen	125	23"	Douglas-fir	20'		N		Asymmetric
N	Onsite	Specimen	126	18"	Oregon oak	26'				
Y	Onsite	Landmark	127	14,16,18"	Oregon oak	17'				Multiple leaders
N	Onsite	Specimen	128	18"	Oregon oak	20'				Trunk wound
Y	Onsite	Specimen	129	13"	Oregon oak	16'		N		Double leaders
Y	Offsite	Offsite	130	18"	Oregon oak	25'				
Y	Offsite	Offsite	131	32"	Oregon oak	34'				
N	Onsite	Specimen	132	19"	Oregon oak	30'				
Y	Offsite	Offsite	134	20"	Oregon oak	28'				
Y	100' WB	Specimen	135	21"	Oregon oak	30'		N		Lean
Y	Offsite	Offsite	136	(5) 20-36"	Bigleaf maple	55'		N		Multiple leaders
Y	Offsite	Offsite	137	17"	Oregon oak	20'		N		Lean, asymmetric
Y	Offsite	Offsite	138	24"	Oregon oak	25'				
Y	Offsite	Street Tree	8000	17	Autumnalis flowering cherry	16'	N			Branch dieback from brown fungus infection
Y	Offsite	Street Tree	8001	15	Autumnalis flowering cherry	16'	N			Branch dieback from brown fungus infection
Y	Offsite	Street Tree	8002	17	Autumnalis flowering cherry	16'	N			Branch dieback from brown fungus infection
Y	Offsite	Street Tree	8003	17	Autumnalis flowering cherry	16'	N			Branch dieback from brown fungus infection

David Rich, Mustard Seed Legacy Development, LLC

RE: Champions Centre Arborist Report, DuPont WA

September 6, 2023



Page 20 of 27

Retain Tree?	Location	Category	Tree No.	DBH	Species	Dripeline (R')	Healthy?	Well formed?	Safe?	Comments on Condition
Y	Offsite	Street Tree	8004	12	Autumnalis flowering cherry	16'	N			Branch dieback from brown fungus infection
Y	Offsite	Street Tree	8005	13	Autumnalis flowering cherry	16'	N			Branch dieback from brown fungus infection
Y	Offsite	Street Tree	8006	18	Kwanzan flowering cherry	20		N		Asymmetric, grows over street
Y	Offsite	Street Tree	8007	13	Kwanzan flowering cherry	14		N		Asymmetric, suppressed canopy
Y	Offsite	Street Tree	8008	15	Kwanzan flowering cherry	14		N		Asymmetric, suppressed canopy
Y	Offsite	Street Tree	8009	19	Kwanzan flowering cherry	14		N		Asymmetric, suppressed canopy
N	Offsite	Street Tree	8010	22	Kwanzan flowering cherry	16		N		Asymmetric, grows over street
Y	Offsite	Street Tree	8011	24	Kwanzan flowering cherry	20		N		Asymmetric, grows over street
N	Offsite	Street Tree	8012	15	Kwanzan flowering cherry	10	N	N	N	Dead
Y	Offsite	Street Tree	8013	20	Kwanzan flowering cherry	18		N		Asymmetric, grows over street
Y	Offsite	Street Tree	8014	18	Oregon ash	22				Multiple trunk injuries (from vehicles)

David Rich, Mustard Seed Legacy Development, LLC
RE: Champions Centre Arborist Report, DuPont WA
September 6, 2023
Page 21 of 27



ATTACHMENT NO. 4 – Photographs of Landmark-Size Hazard Trees

Tree No.	DBH	Species	Comments on Condition
2	13,20,24"	Bigleaf maple	Multiple leaders along trunk axis, previous leader failure and open wound with decay, included bark with response wood present



David Rich, Mustard Seed Legacy Development, LLC
RE: Champions Centre Arborist Report, DuPont WA
September 6, 2023
Page 22 of 27

Tree No.	DBH	Species	Comments on Condition
22	56"	Douglas-fir	Recent failure of the top of the tree, trunk decay visit at failure, 7.5" sound wood at base observed after extracting a wood core (75% of radius is decayed wood), scaffold branch failure in upper canopy at previous topping wound, dead hanging branch in upper canopy




David Rich, Mustard Seed Legacy Development, LLC

RE: Champions Centre Arborist Report, DuPont WA

September 6, 2023

Page 23 of 27

Tree No.	DBH	Species	Comments on Condition
63	32"	Douglas-fir	Resin oozing on lower portion of trunk, 6" sound wood from removed core (66% of radius is decayed wood), then discolored wood further in trunk, very thin foliage, some branch dieback, and suspect root rot infection.




David Rich, Mustard Seed Legacy Development, LLC

RE: Champions Centre Arborist Report, DuPont WA

September 6, 2023


Page 24 of 27

Tree No.	DBH	Species	Comments on Condition
66	33"	Douglas-fir	Previous rootplate failure and with an obvious sweep in the trunk, low LCR, thin branches throughout canopy



David Rich, Mustard Seed Legacy Development, LLC
RE: Champions Centre Arborist Report, DuPont WA
September 6, 2023
Page 25 of 27

Tree No.	DBH	Species	Comments on Condition
67	(11) 9-26"	Bigleaf maple	Multiple leaders at single attachment near grade (tree was likely cut to grade decades ago), bark inclusions present at most attachments, previous failure of structural branches, <i>Ganoderma</i> fungus fruiting bodies on lower trunk.




David Rich, Mustard Seed Legacy Development, LLC

RE: Champions Centre Arborist Report, DuPont WA

September 6, 2023

Page 26 of 27

Tree No.	DBH	Species	Comments on Condition
77	24"	Oregon oak	Dense ivy covering trunk, trunk leans and with bow, asymmetric structure, deadwood throughout canopy, thin branches, low LCR.



David Rich, Mustard Seed Landscaping Development, LLC
RE: Champions Centre Arborist Report, Dupont WA
September 6, 2023
Page 27 of 27
ATTACHMENT NO. 5 - Tree Retention Plan



GRAPHIC SCALE
1 INCH = 40 FEET

CHAMPIONS CENTRE TREE RETENTION PLAN

A PORTION OF THE SE $\frac{1}{4}$ OF THE SW $\frac{1}{4}$ OF SECTION 25 AND NE $\frac{1}{4}$ OF SECTION 26, TOWNSHIP 19 N, RANGE 4 E, W.M.
CITY OF DUPONT, PIERCE COUNTY, WASHINGTON

PARCEL NUMBERS:
0119362039, 0119362030, 0119362012 & 0119362043
PARCEL AREA:
527.527 S.F. (12.82 Ac)
SURVEY DISCLAIMER:
This is not a boundary survey

RETAIN	CAT.	NAME #	SIZE (IN.)	SPACING	SHADING
N	Maple	1	12.50" x 24"	High risk maple	01
N	Maple	2	12.50" x 24"	High risk maple	02
N	Maple	3	12.50" x 24"	High risk maple	03
Y	Deciduous	4	12"	Deciduous oak	04
Y	Deciduous	5	12"	Deciduous oak	05
Y	Deciduous	6	12"	Deciduous oak	06
Y	Deciduous	7	12"	Deciduous oak	07
Y	Deciduous	8	12"	Deciduous oak	08
Y	Deciduous	9	12"	Deciduous oak	09
Y	Deciduous	10	12"	Deciduous oak	10
Y	Deciduous	11	12"	Deciduous oak	11
Y	Deciduous	12	12"	Deciduous oak	12
Y	Deciduous	13	12"	Deciduous oak	13
Y	Deciduous	14	12"	Deciduous oak	14
Y	Deciduous	15	12"	Deciduous oak	15
Y	Deciduous	16	12"	Deciduous oak	16
Y	Deciduous	17	12"	Deciduous oak	17
Y	Deciduous	18	12"	Deciduous oak	18
Y	Deciduous	19	12"	Deciduous oak	19
Y	Deciduous	20	12"	Deciduous oak	20
Y	Deciduous	21	12"	Deciduous oak	21
Y	Deciduous	22	12"	Deciduous oak	22
Y	Deciduous	23	12"	Deciduous oak	23
Y	Deciduous	24	12"	Deciduous oak	24
Y	Deciduous	25	12"	Deciduous oak	25
Y	Deciduous	26	12"	Deciduous oak	26
Y	Deciduous	27	12"	Deciduous oak	27
Y	Deciduous	28	12"	Deciduous oak	28
Y	Deciduous	29	12"	Deciduous oak	29
Y	Deciduous	30	12"	Deciduous oak	30
Y	Deciduous	31	12"	Deciduous oak	31
Y	Deciduous	32	12"	Deciduous oak	32
Y	Deciduous	33	12"	Deciduous oak	33
Y	Deciduous	34	12"	Deciduous oak	34
Y	Deciduous	35	12"	Deciduous oak	35
Y	Deciduous	36	12"	Deciduous oak	36
Y	Deciduous	37	12"	Deciduous oak	37
Y	Deciduous	38	12"	Deciduous oak	38
Y	Deciduous	39	12"	Deciduous oak	39
Y	Deciduous	40	12"	Deciduous oak	40
Y	Deciduous	41	12"	Deciduous oak	41
Y	Deciduous	42	12"	Deciduous oak	42
Y	Deciduous	43	12"	Deciduous oak	43
Y	Deciduous	44	12"	Deciduous oak	44
Y	Deciduous	45	12.50" x 24"	High risk maple	45
Y	Deciduous	46	12"	Deciduous oak	46
Y	Deciduous	47	12"	Deciduous oak	47
Y	Deciduous	48	12"	Deciduous oak	48
Y	Deciduous	49	12"	Deciduous oak	49
Y	Deciduous	50	12"	Deciduous oak	50
Y	Deciduous	51	12"	Deciduous oak	51
Y	Deciduous	52	12"	Deciduous oak	52
Y	Deciduous	53	12"	Deciduous oak	53
Y	Deciduous	54	12"	Deciduous oak	54
Y	Deciduous	55	12"	Deciduous oak	55
Y	Deciduous	56	12"	Deciduous oak	56
Y	Deciduous	57	12"	Deciduous oak	57
Y	Deciduous	58	12"	Deciduous oak	58
Y	Deciduous	59	12"	Deciduous oak	59
Y	Deciduous	60	12"	Deciduous oak	60
Y	Deciduous	61	12"	Deciduous oak	61
Y	Deciduous	62	12"	Deciduous oak	62
Y	Deciduous	63	12"	Deciduous oak	63
Y	Deciduous	64	12"	Deciduous oak	64
Y	Deciduous	65	12"	Deciduous oak	65
Y	Deciduous	66	12"	Deciduous oak	66
Y	Deciduous	67	12"	Deciduous oak	67
Y	Deciduous	68	12"	Deciduous oak	68
Y	Deciduous	69	12"	Deciduous oak	69
Y	Deciduous	70	12"	Deciduous oak	70
Y	Deciduous	71	12"	Deciduous oak	71
Y	Deciduous	72	12"	Deciduous oak	72
Y	Deciduous	73	12"	Deciduous oak	73
Y	Deciduous	74	12"	Deciduous oak	74
Y	Deciduous	75	12"	Deciduous oak	75
Y	Deciduous	76	12"	Deciduous oak	76
Y	Deciduous	77	12"	Deciduous oak	77
Y	Deciduous	78	12"	Deciduous oak	78
Y	Deciduous	79	12"	Deciduous oak	79
Y	Deciduous	80	12"	Deciduous oak	80
Y	Deciduous	81	12"	Deciduous oak	81
Y	Deciduous	82	12"	Deciduous oak	82
Y	Deciduous	83	12"	Deciduous oak	83
Y	Deciduous	84	12"	Deciduous oak	84
Y	Deciduous	85	12"	Deciduous oak	85
Y	Deciduous	86	12"	Deciduous oak	86
Y	Deciduous	87	12"	Deciduous oak	87
Y	Deciduous	88	12"	Deciduous oak	88
Y	Deciduous	89	12"	Deciduous oak	89
Y	Deciduous	90	12"	Deciduous oak	90
Y	Deciduous	91	12"	Deciduous oak	91
Y	Deciduous	92	12"	Deciduous oak	92
Y	Deciduous	93	12"	Deciduous oak	93
Y	Deciduous	94	12"	Deciduous oak	94
Y	Deciduous	95	12"	Deciduous oak	95
Y	Deciduous	96	12"	Deciduous oak	96
Y	Deciduous	97	12"	Deciduous oak	97
Y	Deciduous	98	12"	Deciduous oak	98
Y	Deciduous	99	12"	Deciduous oak	99
Y	Deciduous	100	12"	Deciduous oak	100
Y	Deciduous	101	12"	Deciduous oak	101
Y	Deciduous	102	12"	Deciduous oak	102
Y	Deciduous	103	12"	Deciduous oak	103
Y	Deciduous	104	12"	Deciduous oak	104
Y	Deciduous	105	12"	Deciduous oak	105
Y	Deciduous	106	12"	Deciduous oak	106
Y	Deciduous	107	12"	Deciduous oak	107
Y	Deciduous	108	12"	Deciduous oak	108
Y	Deciduous	109	12"	Deciduous oak	109
Y	Deciduous	110	12"	Deciduous oak	110
Y	Deciduous	111	12"	Deciduous oak	111
Y	Deciduous	112	12"	Deciduous oak	112
Y	Deciduous	113	12"	Deciduous oak	113
Y	Deciduous	114	12"	Deciduous oak	114
Y	Deciduous	115	12"	Deciduous oak	115
Y	Deciduous	116	12"	Deciduous oak	116
Y	Deciduous	117	12"	Deciduous oak	117
Y	Deciduous	118	12"	Deciduous oak	118
Y	Deciduous	119	12"	Deciduous oak	119
Y	Deciduous	120	12"	Deciduous oak	120
Y	Deciduous	121	12"	Deciduous oak	121
Y	Deciduous	122	12"	Deciduous oak	122
Y	Deciduous	123	12"	Deciduous oak	123
Y	Deciduous	124	12"	Deciduous oak	124
Y	Deciduous	125	12"	Deciduous oak	125
Y	Deciduous	126	12"	Deciduous oak	126
Y	Deciduous	127	12"	Deciduous oak	127
Y	Deciduous	128	12"	Deciduous oak	128
Y	Deciduous	129	12"	Deciduous oak	129
Y	Deciduous	130	12"	Deciduous oak	130
Y	Deciduous	131	12"	Deciduous oak	131
Y	Deciduous	132	12"	Deciduous oak	132
Y	Deciduous	133	12"	Deciduous oak	133
Y	Deciduous	134	12"	Deciduous oak	134
Y	Deciduous	135	12"	Deciduous oak	135
Y	Deciduous	136	12"	Deciduous oak	136
Y	Deciduous	137	12"	Deciduous oak	137
Y	Deciduous	138	12"	Deciduous oak	138
Y	Deciduous	139	12"	Deciduous oak	139
Y	Deciduous	140	12"	Deciduous oak	140
Y	Deciduous	141	12"	Deciduous oak	141
Y	Deciduous	142	12"	Deciduous oak	142
Y	Deciduous	143	12"	Deciduous oak	143
Y	Deciduous	144	12"	Deciduous oak	144
Y	Deciduous	145	12"	Deciduous oak	145
Y	Deciduous	146	12"	Deciduous oak	146
Y	Deciduous	147	12"	Deciduous oak	147
Y	Deciduous	148	12"	Deciduous oak	148
Y	Deciduous	149	12"	Deciduous oak	149
Y	Deciduous	150	12"	Deciduous oak	150
Y	Deciduous	151	12"	Deciduous oak	151
Y	Deciduous	152	12"	Deciduous oak	152
Y	Deciduous	153	12"	Deciduous oak	153
Y	Deciduous	154	12"	Deciduous oak	154
Y	Deciduous	155	12"	Deciduous oak	155
Y	Deciduous	156	12"	Deciduous oak	156
Y	Deciduous	157	12"	Deciduous oak	157
Y	Deciduous	158	12"	Deciduous oak	158
Y	Deciduous	159	12"	Deciduous oak	159
Y	Deciduous	160	12"	Deciduous oak	160
Y	Deciduous	161	12"	Deciduous oak	161
Y	Deciduous	162	12"	Deciduous oak	162
Y	Deciduous	163	12"	Deciduous oak	163
Y	Deciduous	164	12"	Deciduous oak	164
Y	Deciduous	165	12"	Deciduous oak	165
Y	Deciduous	166	12"	Deciduous oak	166
Y	Deciduous	167	12"	Deciduous oak	167
Y	Deciduous	168	12"	Deciduous oak	168
Y	Deciduous	169	12"	Deciduous oak	169
Y	Deciduous	170	12"	Deciduous oak	170
Y	Deciduous	171	12"	Deciduous oak	171
Y	Deciduous	172	12"	Deciduous oak	172
Y	Deciduous	173	12"	Deciduous oak	173
Y	Deciduous	174	12"	Deciduous oak	174
Y	Deciduous	175	12"	Deciduous oak	175
Y	Deciduous	176	12"	Deciduous oak	176
Y	Deciduous	177	12"	Deciduous oak	177
Y	Deciduous	178	12"	Deciduous oak	178
Y	Deciduous	179	12"	Deciduous oak	179
Y	Deciduous	180	12"	Deciduous oak	180
Y	Deciduous	181	12"	Deciduous oak	181
Y	Deciduous	182	12"	Deciduous oak	182
Y	Deciduous	183	12"	Deciduous oak	183
Y	Deciduous	184	12"	Deciduous oak	184
Y	Deciduous	185	12"	Deciduous oak	185
Y	Deciduous	186	12"	Deciduous oak	186
Y	Deciduous	187	12"	Deciduous oak	187
Y	Deciduous	188	12"	Deciduous oak	188
Y	Deciduous	189	12"	Deciduous oak	189
Y	Deciduous	190	12"	Deciduous oak	190
Y	Deciduous	191	12"	Deciduous oak	191
Y	Deciduous	192	12"	Deciduous oak	192
Y	Deciduous	193	12"	Deciduous oak	193
Y	Deciduous	194	12"	Deciduous oak	194
Y	Deciduous	195	12"	Deciduous oak	195
Y	Deciduous	196	12"	Deciduous oak	196
Y	Deciduous	197	12"	Deciduous oak	197
Y	Deciduous	198	12"	Deciduous oak	198
Y	Deciduous	199	12"	Deciduous oak	199
Y	Deciduous	200	12"	Deciduous oak	200
Y	Deciduous	201	12"	Deciduous oak	201
Y	Deciduous	202	12"	Deciduous oak	202
Y	Deciduous	203	12"	Deciduous oak	203
Y	Deciduous	204	12"	Deciduous oak	204
Y	Deciduous	205	12"	Deciduous oak	205
Y	Deciduous	206	12"	Deciduous oak	206
Y	Deciduous	207	12"	Deciduous oak	207
Y	Deciduous	208	12"	Deciduous oak	208
Y	Deciduous	209	12"	Deciduous oak	209
Y	Deciduous	210	12"	Deciduous oak	210
Y	Deciduous	211	12"	Deciduous oak	211
Y	Deciduous	212	12"	Deciduous oak	212
Y	Deciduous	213	12"	Deciduous oak	213
Y	Deciduous	214	12"	Deciduous oak	214
Y	Deciduous	215	12"	Deciduous oak	215
Y	Deciduous				